# REVISED NON-SUBSTANTIVE PROPOSED CODE CHANGES 2004 CODE CYCLE

## **Proposed Amendment**

#### PART 2 - CHAPTER 2 -- DEFINITIONS AND ABBREVIATIONS

#### SECTION 217 - P

PUBLIC USE AREA. [For HCD 1/AC] See Chapter 11A, Section 1102A.16-P. [For DSA/AC] See Chapter 11A, Section 1102A.16-P 1107A.16-P and Chapter 11B, Section 1102B.

#### SECTION 219 - R

[For HCD 1/AC, DSA/AC] RAMP. See Chapter 11A, Section 1102A.18-R 1107A.18-R.

RISER. [For HCD 1/AC] See Chapter 11A, Section 1102A.18-R. [For DSA/AC] See Chapter 11A, Section 1102A.18-R 1107A.18R and Chapter 11B, Section 1102B.

## SECTION 220 - S

**SLEEPING ACCOMMODATIONS.** [For HCD 1/AC] See Chapter 11A, Section 1102A.19-S. [For DSA/AC] See Chapter 11A, Section 1102A.19-S and Chapter 11B, Section 1102B.

[For HCD 1/AC, DSA/AC] SLOPE. See Chapter 11A, Section 4102A.19-S 1107A.19-S.

SPECIAL ACCESS LIFT. [For HCD 1/AC] See Chapter 11A, Section 1102A.19-S. [For DSA/AC] See Chapter 11A, Section 1102A.19-S. 1107A.19-S and Chapter 11B, Section 1102B.

[For HCD 1/AC, DSA/AC] STAIR RAILING. See Chapter 11A, Section 1102A.19-S 1107A.19-S.

#### SECTION 221 - T

[[For HCD 1/AC, DSA/AC] TOEBOARD. See Chapter 11A, Section 1102A.20-T 1107A.20-T.

[For HCD 1/AC, DSA/AC] TOWNHOUSE. See Chapter 11A, Section 1102A.20-T 1107A.20-T...

**TREAD.** [For HCD 1/AC] See Chapter 11A, Section 1102A.20-T. [For DSA/AC] See Chapter 11A, Section 1102A.20-T 1107A.20-T and Chapter 11B, Section 1102B.

**TREAD DEPTH.** [For HCD1/AC] See Chapter 11A, Section 1102A.20-T. [For DSA/AC] See Chapter 11A, Section 1102A.20-T. 1107A.20-T and Chapter 11B, Section 1102B.

TREAD RUN. [For HCD 1/AC] See Chapter 11A, Section 1102A.20-T. [For DSA/AC] See Chapter 11A, Section 1102A.20-T 1107A.20-T and Chapter 11B, Section 1102B.

#### SECTION 223 - V

[For HCD 1/AC, DSA/AC] VEHICULAR OR PEDESTRIAN ARRIVAL POINTS. See Chapter 11A, Section 1102.22-V 1107A.22-V.

## SECTION 224 -- W

WALK. [For HCD 1/AC] See Chapter 11A, Section 1102A.23-W. [For DSA/AC] See Chapter 11A, Section 1102A.23-W 1107A.23-W and Chapter 11B, Section 1102B.

### Reason

Several definitions in Chapter 2 cross-reference Chapter 11A. HCD is renumbering 11A regulations. DSA/AC is amending the cross-references to be consistent with the new numbering formation of Chapter 11A.

Notes:		

## PART 2 - CHAPTER 10 -- MEANS OF EGRESS

**SECTION 1003 - GENERAL** 

1003.2 System Design Requirements.

1003.2.8 Means of Egress Identification.

**1003.2.8.6** [For DSA/AC] Tactile Exit Signage. For the purposes of Section 1003.2.8.6, the term "tactile exit signs" shall mean those required signs that comply with Section 1117B.5.1 Item 1 1117B.5.1-B.

#### Reason

In **1003.2.8.6 (Tactile Exit Signage)** cross-reference to 1117B.5.1-B is incorrect. Cross-reference should read 1117B.5.1 Item 1. DSA/AC is proposing to correct the cross-reference.

Notes:			

#### **Proposed Amendment**

## PART 2 - CHAPTER 10 -- MEANS OF EGRESS

**SECTION 1003 - GENERAL** 

1003.3 Means of egress components.

1003.3.1 Doors.

1003.3.1.3 Width and height.

[For DSA/AC] NOTE: For accessibility requirements for width and height of doors in housing accessibility, see Chapter 11A, Sections 1120A.2.2 1126A.1 and 1132A.2.1, and for public buildings, public accommodations, commercial buildings and publicly funded housing, see Chapter 11B, Section 1133B.2.2.

#### 1003.3.1.6 Floor Level at Doors

1003.3.1.6.1 [For DSA/AC] Thresholds.

**NOTE:** For accessibility requirements for thresholds in accessible housing, see Chapter 11A, Section 1120A.2.4 1126A.2. 1126A.2.1, 1132A.3 and 1132A.4, and for public buildings, public accommodations, commercial buildings and publicly funded housing, see Chapter 11B, Section 1133B.2.4.1.

1003.3.3 Stairways

1003.3.3.6 Handrails.

1003.3.3.6.1 Handrails.

1003.3.3.6.1.1 [For HCD 1 w/exceptions; HCD 2 w/exceptions 1, 2, 4 and 5; HCD 1/AC w/exception 6] Required handrails.

**[For DSA/AC] NOTE:** For Accessibility requirements for handrails in accessible housing, see Chapter 11A, Section 1120A.4.1 1123A.6.1, and for public buildings, public accommodations, commercial buildings and publicly funded housing, see Chapter 11B, Section 1133B.4.1.1.

## Reason

Several cross-references in Chapter 10 are incorrect, as HCD is renumbering 11A regulations. DSA/AC is amending the cross-references to be consistent with the new numbering formation of Chapter 11A.

Notes:		

Proposed Amendment
PART 2 – CHAPTER 10 MEANS OF EGRESS
SECTION 1003 – GENERAL
1003.3 Means of egress components
1003.3.1 Doors
1003.3.1.8 Type of lock or latch. Regardless of the occupant
EXCEPTIONS: 1. In Groups A
2. Exit doors from
3. [for SFM] Mental, penal or corrective
[For SFM & DSA/AC] Bars, grilles, grates, or similar devices
Manually operated edge- or
EXCEPTIONS: 1. Group R, Division
2. Where a pair
[For DSA/AC] NOTE: For accessibility requirements for type of lock or latch in public buildings, public
accommodations, commercial buildings and publicly funded housing, see Chapter 11B, section 1133B.2.1.
Reason

In 1003.3.1.8 (Type of lock or latch) cross-reference to DSA/AC adoption of paragraph #2 [Bars, grilles, grates ...] was mistakenly left out of the publication of the 2001 California Building Code. DSA/AC is proposing to correctly cross-reference DSA/AC by adding cross-reference adoption indicator to paragraph #2 [Bars, grilles, grates ...]. Also, the cross-reference Note is shown in error. The provisions for type of lock or latch were intended to be relocated to Chapter 11B, but instead were not relocated. DSA/AC adopts 1003.3.1.8 without the note. DSA/AC is proposing to delete the cross-reference note in 1003.3.1.8.

Notes:	

#### PART 2 - CHAPTER 10 -- MEANS OF EGRESS

**SECTION 1003 - GENERAL** 

1003.3 Means of egress components

1003.3.1 Doors

1003.3.1.10 Special egress-control devices. When approved by the ...

Shall conform to the following:

- 1. The egress-control device shall ...
- 2. The egress-control device shall ...
  - 2.1 The egress-control device itself.
  - 2.2 The smoke-detection device itself.
  - 2.3 Means of egress illumination ...
- **3.** The egress-control device shall ...
- **4.** An irreversible process that ...
- **5.** Actuation of the panic ...
- 6. The unlatching shall not ...

A sign shall be provided on the door located above and within 12 inches (305 mm) of the panic bar or other door-latching hardware reading:

"KEEP PUSHING. THIS DOOR WILL OPEN IN

SECONDS. ALARM WILL SOUND"

Sign lettering shall be at least ...

Regardless of the means of deactivation, ...

<u>NOTE 1</u>: [For SFM & DSA/AC] A tactile sign shall also be provided in Braille and raised Characters, which complies with Section 1117B.5.1 Item 1 1117B.5.1-B.

#### Reason

In **1003.3.1.10 (Special egress-control devices)** paragraph 5 is adopted by DSA/AC but is incorrectly shown as a paragraph. Paragraph 5 should appear as a cross-reference Note. The reference in paragraph 5 to 1117B.5.1-B is incorrect. DSA/AC is proposing to make paragraph 5 a Note and to correct the cross-reference to read 1117B.5.1 Item 1.

Notes:		

## **Proposed Amendment**

PART 2 - CHAPTER 10 -- MEANS OF EGRESS

**SECTION 1003 -- GENERAL** 

1003.3 Means of egress components

1003.3.3 Stairways

1003.3.3.13 Stairway identification.

**1003.3.3.13.1** [For DSA/AC] Tactile stair level identification sign. Tactile stair level identification sings that comply with <u>1117B.5.1 Item 1 4117B.5.1-B</u> shall be located at each floor level landing in all ... height of the raised characters.

#### Reason

In **1003.3.3.13.1 (Tactile stair level identification sign)** cross-reference to 1117B.5.1-B is incorrect. Cross-reference should read 1117B.5.1 Item 1. DSA/AC is proposing to correct the cross-reference.

Notes:			

#### PART 2 - CHAPTER 10 -- MEANS OF EGRESS

### **SECTION 1003 -- GENERAL**

1003.3 Means of egress components

1003.3.4 Ramps.

Notes:

**1003.3.4.4 Landings.** Ramps having slopes steeper than 1 unit vertical in 20 units horizontal (5% slope) shall have landings at the top and bottom, and a t least one intermediate landing shall be provided for each 5 feet (1524 mm) of vertical is measured between the horizontal planes of adjacent landings. Top landings and intermediate landings shall have a dimension measured in the direction of ramp run of not less than 5 feet (1524 mm). Landings at the bottom of ramps shall have a dimension in the direction of ramp run of not less than 6 feet (1829 mm).

## NOTE: [For DSA/AC] paragraph one is not adopted by DSA/AC.

Doors in any position shall not reduce he minimum dimension of the landing of less than 42 inches (1067 mm) and shall not reduce the required width by more than 7 inches (178 mm) [for HCD 1/AC, DSA/AC] 3 inches (76 mm) when fully open.

Where ramp access is provided to comply with the requirements of Chapter 11 and a door swings over a landing, the landing shall extend at least 24 inches (610 mm) beyond the latch edge of the door, measured parallel to the door in the closed position, and shall have a length measured in the direction of travel through the doorway of of less than 5 feet (1524 mm).

## NOTE: [For DSA/AC] paragraph three is not adopted by DSA/AC.

**[For DSA/AC] NOTE:** For accessibility requirements for landings in public buildings, public accommodations, commercial buildings and publicly funded housing, see Chapter 11B, Section 1133B.5.4.1.

#### Reason

In **1003.3.4.4 (Landings)** paragraphs 1 and 3 are a violation of CA law. Paragraphs 1 and 3 are not adopted by DSA/AC. Paragraph 2 is adopted by DSA/AC therefore DSA/AC is proposing to add our adoption to be consistent with HCD adoption for 3-inches to clearly identify which provisions for landings DSA/AC adopts. In 1003.3.4.4 the Note is shown in error, provisions for doors were intended to be relocated to Chapter 11B, but remained in Chapter 10. DSA/AC is proposing to delete the Note in 1003.3.4.4.

Notes:
Proposed Amendment
1 Topossa Amerianism
PART 2 - CHAPTET 10 MEANS OF EGRESS
SECTION 1005 – THE EXIT
<b>1005.1 [For DSA/AC] General.</b> The exit is that portion of the means of egress system between the exit access and the exit discharge or the public way. Components that may be selectively included in the exit include exterior exit
doors exit enclosures, exit passageways and horizontal exits, in addition to those common means of egress
components described in Section 1003.3.
_
Reason
In 1005.1 (General) the cross-reference indicating DSA/AC adoption of section 1005, subsection 1005.1 was
mistakenly left out of the publication of the 2001 California Building Code. DSA/AC adopts 1005.1 by reference in the
definition of Exit in Chapter 2. DSA/AC is proposing to correctly cross-reference DSA/AC by adding cross-reference
adoption indicator.

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1102B – DEFINITIONS

LIFT, SPECIAL ACCESS. See "Special Access Lift."

NEWLY CONSTRUCTED. See Chapter 11A, Section 1107A.14-N.

PUBLIC USE AREA. See Chapter 11A, Section 1107A.16-P.

## Reason

In **1102B (Definitions)** there is an inconsistency in the cross-references to the definitions of "Lift, Special Access", "Newly Constructed" and "Public Use Area" between Chapters 2, 11A and 11B. These definitions were mistakenly left out of Chapter 11B. These definitions refer to Chapters 11A and 11B in Chapter 2 (Definitions and Abbreviations). For consistency between Chapters 2, 11A and 11B DSA/AC is proposing to include the definitions for Lift, Special Access, Newly Constructed, and Public Use Area with cross-references in Chapter 11B to 11A to be consistent with the new numbering format of HCD.

Notes:		

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

#### SECTION 1103B - BUILDING ACCESSIBILITY

1103B.1 General. Accessibility to buildings or ...

#### **EXCEPTIONS:**

- 1. This section shall ...
- 2. Floors or portions of floors not customarily occupied, including, but not limited to, nonoccupiable or employee spaces accessed only by ladders, catwalks, crawl spaces, very narrow passageways or freight (nonpasssenger) elevators, and frequented only by service personnel for repair or maintenance purposes: such spaces as elevator pits and elevator penthouses, piping and equipment catwalks and machinery rooms. Stair stripping striping shall be required on stairs.
- 3. The following ...

#### Reason

In **1103B.1**, **Exception 2**, last sentence, the word 'stripping' is spelled incorrectly. DSA/AC is proposing to correct the spelling to read 'stripping'. The last sentence is corrected to read: Stair stripping shall be required on stairs.

Notes:			

## **Proposed Amendment**

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

## SECTION 1104B - ACCESSIBILITY FOR GROUP A OCCUPANCIES

1104B.4 Stadiums, Grandstands, Bleachers, Athletic Pavilion, Gymnasiums and Miscellaneous Sport-related Facilities.

- 1104B.4.3 Participation areas. Participation areas shall be ...:
  - 1. Tennis, racquetball ...
  - 2. Gymnasium floor ...
  - 3. Basketball, volleyball ...
  - 4. Swimming pool deck ...
    - **4.1** Have a seat that meets all of the following:
      - **4.1.1** The seat ...
      - **4.1.2** The seat ...
      - **4.1.3** The seat ...
      - **4.1.4** The seat ...
      - **4.1.5** The seat must have an occupant restraint for use by the occupant of the seat, and the restraint must meet the standards for operable controls in compliance with Section 1117B.6 with Items 1—4 1117B.6-4.
    - 4.2 Be capable of ...
    - 4.3 Be stable and ...
    - 4.4 Be designed to ...
    - 4.5 Be positioned so that, ...
    - **4.6** Lower the operator ...
  - 5. Athletic team rooms ...

#### Reason

In **1104B.4.3 (Participation areas)** Item 4.1.5 the cross-reference to 1117B.6-4 is incorrect. DSA/AC is proposing to correct cross-reference to read 1117B.6 with Items 1—4.

Notes:			

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

# SECTION 1104B – ACCESSIBILITY FOR GROUP A OCCUPANCIES 1104B.5 Dining. Banquet and Bar Facilities.

1. General. Dining. banquet. ...

#### **EXCEPTIONS:**

- 1. In existing buildings, when ...
- 2. In existing ... See Section 101.17.11, Item 5 Item 4.
- 2. Entrance. ...
- 3. Functional activity. ...
- 4. Seating. ...
- 5. Food service aisles. ...
- 6. Tableware areas. ...
- 7. Restrooms. ...
- **8. Food preparation areas.** Access to food preparation areas shall comply with the provisions for entrance doors and doorways in Section 1133B.2.2 1004, and aisles in Sections 1133B.6 1004.3.2.1 and 1004.3.2.2.

#### Reason

In 1104B.5 (Dining, Banquet and Bar Facilities) #1 (General) Exception 2 cross-reference to Section 101.17.11, Item 4 is incorrect. DSA/AC is proposing to correct cross-reference to read Item 5.

In **1104B.5 (Dining, Banquet and Bar Facilities)** #8 (Food preparation areas) cross-references to 1004, 1004.3.2.1 and 1004.3.2.2 are incorrect. DSA/AC is proposing to correct cross-references to read 'Section 1133B.2.2, and aisles in Sections 1133B.6.'

Notes:			

# Proposed Amendment

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

## SECTION 1105B - ACCESSIBILITY FOR GROUP B OCCUPANCIES

Group B Occupancies shall be accessible as provided in this chapter. See also the general requirements listed in Section 1114B.1.1.

## **EXCEPTIONS:**

- 1. In existing buildings, when the ... facilitation is provided.
- 2. In existing buildings, the provisions... hardship. See Section 101.17.11, Item 5 Item 4
- 3. For floors and levels in new and existing buildings, see Section 1120B.

#### Reason

In 1105B (Accessibility for Group B Occupancies) in Exception 2 cross-reference to Section 101.17.11, Item 4 is incorrect. DSA/AC is proposing to correct cross-reference to read 101.17.11 Item 5.

l	Notes:
l	
1	

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

#### SECTION 1106B - ACCESSIBILITY FOR GROUP E OCCUPANCIES

**1106B.1 General.** Group E Occupancies shall be accessible as provided in this chapter. See also the general requirements listed in Section 1114B.1.1.

#### **EXCEPTIONS:**

- 1. In existing buildings, when the...
- 2. In existing buildings, where ... See Section101.17.11, Item 5 Item 4.

#### Reason

In **1106B.1 (General)** in Exception 2 cross-reference to "Section 101.17.11, Item 4" is incorrect. DSA/AC is proposing to correct the cross-reference to read 101.17.1 Item 5.

Notes:			

#### **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

#### SECTION 1107B - FACTORIES AND WAREHOUSES

Factories and warehouses shall conform to the provisions of this section, Section 1103B.1 and Section 1103B.1, <u>Exception 3</u>, for multistory buildings.

**EXCEPTION:** In existing buildings,...

#### Reason

In **1107B (Factories and Warehouses)** cross-reference to "Section 1103B.1 Exception 2 is incorrect. DSA/AC is proposing to correct cross-reference to read 1103B.1, Exception 3.

Notes:	

## **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

## SECTION 1108B - ACCESSIBILITY FOR GROUP H OCCUPANCIES

**1108B.1 General.** Group H Occupancies shall be accessible as provided in this chapter. See also the general requirements listed in Section 1114B.1.1.

# **EXCEPTIONS:**

- 1. In existing Group H Occupancies... protection are provided.
- In existing Group H Occupancies, ... unreasonable hardship. See Section 101.17.11, Item 5 Item 4.

#### Reason

In 1108B (Accessibility for Group H Occupancies) in Exception 2 cross-reference to Section 101.17.11, Item 4 is incorrect. DSA/AC is proposing to correct cross-reference to read Item 5

Notes:		

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

## SECTION 1111B - ACCESSIBILITY FOR GROUP R OCCUPANCIES

1111B.4 Hotels, Motels, Inns, Dormitories, Resorts, Homeless Shelters, Halfway Houses, Transient Group Homes and Similar Places of Transient Lodging.

**1111B.4.4 Kitchen facilities.** When accommodations are provided with kitchen units, accessible kitchens shall be provided to those accommodations required to be accessible in conformance with Table 11B-3, and shall meet the requirements of Section <u>1112A</u> <u>1133A</u>.

#### Reason

Several cross-references in Chapter 11B are incorrect, as HCD is renumbering 11A regulations. DSA/AC is amending the cross-references to be consistent with the new numbering formation of Chapter 11A.

Notes:			

## **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

#### SECTION 1114B - FACILITY ACCESSIBILITY

1114B.1 Design and Construction.

**1114B.1.1 General.** When accessibility is required by this chapter, it shall be designed and constructed to meet the minimum requirements of the following sections:

Chapter 11B. Accessibility; Division I, New Buildings; Division II, Site Accessibility; Division III, Accessibility for Entrances, Exits and Paths of Travel; and Division IV, Accessibility for Existing Buildings

Entrances - [for HCD 1/AC] Section 1120A.1; [for DSA/AC] Section 1133B.11

**Doors** – [for HCD 1/AC] Section <del>1120A.2</del> <u>1114A.4.4, 1117A.2, 1122A.3.4, 1126A, 1132A</u>; [for DSA/AC] Section 1133B.2

Corridors – [for HCD 1/AC] Section 1120A.3 1120A; [for DSA/AC] Section 1133B.3

Stairways – [for HCD 1/AC] Section <u>1120A.4</u> 1115A.6, 1123A; [for DSA/AC] Section 1133B.4

Ramps - [for HCD 1/AC] Section 1120A.5 1112A , 1114A , 1122A; [for DSA/AC] Section 1133B.5

Aisles - [for DSA/AC] Section 1133B.6

Walks and Sidewalks - [for HCD 1/AC] Section 1120A.7 1113A; [for DSA/AC] Section 1133B.7

Hazards - [for HCD 1/AC] Section 1120A.7 1116A, 1125A; [for DSA/AC] Section 1133B.8

Elevators - [for HCD 1/AC] Section 3003; [for DSA/AC] Section 1116B.

Special Access (Wheelchair) Lifts – [for HCD 1/AC] Section 1110A.2 1124A; [for DSA/AC] Section 1116B.2 Alarms – Chapter 35.

#### Reason

In **1114B.1.1 (General)** the cross-reference in "Entrances" to Section 1133B is incorrect. DSA/AC is proposing to correct the cross-reference to read 1133B.1.1. All cross-references to Chapter 11A are incorrect. DSA/AC is proposing to correct all Chapter 11A references to be consistent with HCD amendments in 11A. DSA/AC is proposing to add a cross-reference to 1116B (Elevators and Special Access (Wheelchair) Lifts).

Notes:		

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

#### **SECTION 1115B – BATHING AND TOILET FACILITIES**

1115B.2 Toilet Facilities.

1115B.2.1 Accessible water closets.

1. The height of accessible ....

**EXCEPTION:** A 3-inch (76 mm)...

2. Controls shall be ...

#### **NOTES:**

- 1. See the California Building Code, Chapter 11A, <u>Section 1134A.7</u> for additional requirements for water closets in publicly funded housing and all nonresidential occupancies.
- 2. Automatic "spring to lifted position" seats are not allowed.

#### 1115B.2.1.1 Accessible urinals.

**1115B.2.1.1.1** Urinals shall be floor mounted or wall hung. Where one or more wall hung urinals are provided provided, at least one with a rim projecting a minimum of 14 inches ...

#### Reason

In 1115B.2.1 (Accessible water closet) in Note 1 under item #2 the cross-reference to Chapter 11A is incorrect. DSA/AC is proposing to correct cross-reference to read Section 1134A.7 to be consistent with HCD Chapter 11A.

In **1115B.2.1.1.1** in the 2<sup>nd</sup> line the word 'provide' is spelled incorrectly. DSA/AC is proposing to correct the spelling of the word to read 'provided' in the 2<sup>nd</sup> sentence.

Notes:			

## **Proposed Amendment**

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

#### SECTION 1115B - BATHING AND TOILET FACILITIES

1115B.2 Toilet Facilities

1115B.2.1 Accessible water closet.

1115B.2.1.3 Accessible showers.

1115B.2.1.3.4 Where, within the ... versus right-hand controls.

NOTE: See the California Building Code, Chapter 11B, for showers in living accommodations.

1115B.2.1.4 Accessible bathtubs. Bathtubs shall be ... mounted on their rims.

NOTE: See the California Building Code, Chapter 11B, for bathtubs in living accommodations.

#### 1115B.2.1.5 Accessible drinking fountains.

**1115B.2.1.5.3** The bubbler shall be activated by ... The water <u>steam</u> from the bubbler shall be substantially parallel to the front edge of the drinking fountain.

#### Reason

In 1115B.2.1.3.4 the cross-referenced Note is incorrect as one is already in the section for 'showers in living accommodations.' DSA/AC is proposing to delete the cross-referenced note.

In 1115B.2.1.4 the cross-referenced Note is incorrect as we are already in the section for 'accessible bathtubs.' DSA/AC is proposing to delete the cross-referenced note.

In 1115B.2.1.5.3 in the last sentence, the word 'steam' is spelled incorrectly. DSA/AC is proposing to correct the spelling to read "stream" in the last sentence.

Notes:		
<u> </u>		

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1115B - BATHING AND TOILET FACILITIES

1115B.2 Toilet Facilities

Notes:

1115B.2.1 Accessible water closet

1115B.2.1.6 Accessible sinks.

**1115B.2.1.6.1 Accessible kitchen sinks.** Faucet controls and operating mechanisms shall be operable with one hand and shall not require tight grasping, pinching or twisting of the wrist. The force required to activate controls shall be not greater than 5 lbf (22.2 N). Lever-operated controls shall be <u>no</u> greater than 5 pound-force (lbf) (22.2 N). Lever-operated, push-type and electronically controlled mechanisms are examples of acceptable designs. Self-closing valves are allowed if the faucet remains open for at least 10 seconds.

1115B.2.1.6.2 Noncommercial kitchen and counter bar sinks. Kitchen and counter bar sinks located in common use areas shall have faucet controls and operating mechanisms operable with one hand in accordance with Chapter 11B of the California Building Code and shall not require grasping, pinching or twisting of the wrist. The force required to activate controls shall be no greater than 5 lbf (22.2 N). Lever-operated, push-type and electronically controlled mechanisms are examples of acceptable designs.

NOTE: See the California Building Code, Chapter 11B.

<u>Diagram 11B-1D</u> <u>This diagram</u> illustrates the specific requirements of the regulations and is intended only as an aid for building, <u>design</u> and construction.

#### Reason

In **1115B.2.1.6.1 (Accessible kitchen sinks)** the 3<sup>rd</sup> sentence is incorrect. DSA/AC is proposing to correct the grammar in the 3<sup>rd</sup> sentence to be consistent with 2<sup>nd</sup> sentence of this section and 1112A.3. Sentence grammar is corrected to read "Lever-operated controls shall be <u>no</u> greater than 5 pound force (lbf) (22.2)."

In 1115B.2.1.6.2 (Noncommercial kitchen and counter bar sinks) the cross-referenced note is incorrect. The cross-reference to 'This diagram' in the 2<sup>nd</sup> paragraph is incorrect. DSA/AC is proposing to delete the cross-referenced note and correct the 2<sup>nd</sup> paragraph to read "<u>Diagram 11B-1D"</u> illustrates the specific requirements of the regulations and is intended only as an aid for building construction. Also, the reference to building and construction is not consistent with the text in Diagram 11B-1D. DSA/AC is proposing to amend the last paragraph to 'building, design and construction' to be consistent with the text on the Diagram.

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

#### **SECTION 1115B – BATHING AND TOILET FACILITIES**

**1115B.5** *Identification Symbols.* Doorways leading ... contrast of the door.

**NOTE:** See also Section <u>1117B.5.1 Item 1</u> <u>1117B.5.7</u> for additional signage requirements applicable to sanitary facilities.

## TABLE 1115B-1 - SUGGESTED DIMENSIONS FOR CHILDREN'S USE

The Division of the State Architect, <u>Access Compliance</u> Office of Regulation Services recommends the following dimensions as adequately serving the needs of children in projects under our jurisdiction. These recommendations are based on the federal "Recommendations for Accessibility for Children in Elementary School" and other recognized publications on access for children:

A = Adult Dimensions (age 12 and over)

*E* = *Elementary Dimensions* 

Notes:

*K* = *Kindergarten* and *Pre-school Dimensions* 

#### Reason

In 1115B.5 (Identification Symbols) the cross-reference to 1117B.5.7 is incorrect. DSA/AC is proposing to correct the cross-reference to read1117B.5.1 Item 1.

In **Table 1115B-1 (Suggested Dimensions for Children' Use)** the cross-reference to the Division of the State Architect, "Office of Regulations Services" is incorrect. DSA/AC is proposing to correct the reference in Table 1115B to read "The Division of the State Architect, Access Compliance recommends the following dimensions ....".

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

**SECTION 1115B - BATHING AND TOILET FACILITIES** 

1115B.6 Bathing Facilities.

1115B.6.2 Showers.

1115B.6.2.4 Accessories.

**1115B.6.2.4.4 Floor slope.** The maximum slope of the floor shall be 2 percent <del>per foot</del> in any direction. Where drains are provided, grate openings shall be a <del>minimum</del> <u>maximum</u> of ¼ inch (6.4 mm) and located flush with the floor surface.

#### Reason

In **1115B.6.2.4.4 (Floor slope)** in the 1<sup>st</sup> sentence the cross reference to '2 percent per foot' is incorrect. DSA/AC is proposing to delete the words 'per foot' which corrects the cross-reference to read '2 percent' in any direction. In the 2nd sentence the word minimum is incorrect. DSA/AC is proposing to correct the sentence to read "maximum" to be consistent with the definition of 'Level Area' in 11B. The definition of Level Area states: "Level Area is a specified surface that does not have a slope in any direction exceeding ¼ inch (6.4)."

Notes:

## **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1116B - ELEVATORS AND SPECIAL ACCESS (WHEELCHAIR) LIFTS

mm) in 1 foot (305 mm) from the horizontal (2,083 percent gradient)."

1116B.1 Elevators.

1116B.1.4 Door size. Minimum clear width for elevator doors shall be 36 inches (914 mm).

**EXCEPTION:** When approved by the building official, the minimum door width may be reduced to 32 inches (813 mm) for a car with dimensions as permitted by the exception to Section 1116B.1.6.

#### Reason

In **1116B.1.4 (Door size)** the exception is inconsistent with the ADA Section 4.10.9 for elevator cab dimensions and Figure 22 which shows 36" min. door opening. DSA/AC is proposing to repeal the exception in 1116B.1.4.

Notes:			

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1116B – ELEVATORS AND SPECIAL ACCESS (WHEELCHAIR) LIFTS 1116B.1 Elevators

1116B.1.8 Car inside. ...

For multiple controls only, one ... If the telephone system is located in a closed compartment, the compartment door hardware shall be lever type conforming to the provisions of Section 1003.3.1.8 1004.3, type of lock or latch. Emergency intercommunication shall not require voice communication.

**NOTE:** Where possible, a 48-inch (1219 mm) maximum height for elevator floor buttons is preferred

## Reason

In **1116B.1.8 (Car inside)** in the last sentence of the 3<sup>rd</sup> paragraph the cross-reference to "Section 1004.3" is incorrect. DSA/AC is proposing to correct the cross-reference to read 1003.3.1.8.

Notes:			
	 renesed Amendm	t	

#### **Proposed Amendment**

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

## SECTION 1116B - SPECIAL ACCESS (WHEELCHAIR) LIFTS

**1116B.2 Special Access** (Wheelchair) Lifts. Special access wheelchair lifts may be provided between levels in lieu of passenger elevators when the vertical distance between landings, as well as the structural design and safeguards are as allowed by the State of California, Division of the State Architect, Access Compliance, the Department of Industrial Relations, Division of Occupational Safety and Health and any applicable safety regulations of other administrative authorities having jurisdiction.

If lifts are provided, they shall be designed and constructed to facilitate unassisted entry, operation and exit from the lift and shall comply with the restrictions and enhancements of this section in conjunction with Sections 3093 to 3094, Part 7, of Title 24, of the California Code of Regulations.

Additionally, lifts may be provided as part of an accessible route only for the following conditions: ...

## Reason

In **1116B.2 (Special Access (Wheelchair) Lifts)** in the 2<sup>nd</sup> paragraph the cross-reference to Sections 3093 to 3094 Part 7 of the California Code of Regulations is incomplete. DSA/AC is proposing to amend the cross-reference to include 'Title 24.'

Notes:		

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

#### **SECTION 1117B - OTHER BUILDING COMPONENTS**

1117B.1 Water Fountains (Drinking)

1117B.1.1 General. Where water fountains are provided, they shall comply with this section.

In new construction, where only one drinking fountain area is provided on a floor, there shall be a drinking fountain that is accessible to individuals who use wheelchairs in accordance with Section 1115B.2.1.5 1115B.2.1.2 and one accessible to those who have difficulty bending or stooping. This can be accommodated by the use of "hi-low" fountains, or by such other means as would achieve the required accessibility for each group on each floor.

1117B.1.2 Alcoves. Water fountains shall be located completely within alcoves or otherwise positioned so as not to encroach into pedestrian ways. The alcove in which the water fountain is located shall not be less than 32 inches (813 mm) in width and 18 inches (457 mm) in depth. See Figure 11B-3 of this code. Protruding objects located in alcoves or otherwise positioned so as to limit encroachment into pedestrian ways are permitted to project 4 inches into walks, walls, halls, corridors, passageways or aisles.

**EXCEPTION:** When the ... he blind as follows:

- 1. The surface of the ... of the water fountain, or
- 2. Wing walls shall be ... the wing walls.

#### Reason

In **1117B.1.1 (General)** in paragraph 2 the cross-reference to "Section 1115B.2.1.2" is incorrect. DSA/AC is proposing to correct the cross-reference to read 1115B.2.1.5.

In 1117B.1.2 the word 'walls' is spelled incorrectly. DSA/AC is proposing to correct the spelling of the word to correctly read 'walks.'

Notes:		

#### **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

**SECTION 1117B – OTHER BUILDING COMPONENTS** 

1117B.2 Telephones.

1117B.2.9 Text telephones.

1117B.2.9.3 Signage. Text telephones shall be identified by the International TTY symbol (see Figure 11B-14A 11B-14). If a facility has a public text telephone, directional signage indicating the location of the nearest such telephone shall be placed adjacent to all banks of telephones that do not contain a text telephone. Such directional signage shall include the International TTY symbol. If a facility has no banks of telephones, the directional signage shall be provided at the entrance or in a building directory.

#### Reason

In **1117B.2.9.3 (Signage)** cross-reference to "Figure 11B-14" is incorrect. DSA/AC is proposing to correct figure cross-reference to read Figure 11B-14A.

Notes:			

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1117B – OTHER BUILDING COMPONENTS

1117B.3 Kitchens. See Section 4112A 1133A.

#### Reason

Several cross-references in Chapter 11B are incorrect, as HCD is renumbering 11A regulations. DSA/AC is amending the cross-references to be consistent with the new numbering formation of Chapter 11A.

Notes:	

## **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

## **SECTION 1117B - OTHER BUILDING COMPONENTS**

1117B.5 Signs and Identification

**1117B.5.7 Mounting location and height.** Where permanent identification is provided for rooms and spaces, signs shall be installed on the wall adjacent to the latch <u>side</u>, <u>outside</u> of the door. Where there is no wall space on the latch side, including at double leaf doors, signs shall be placed on the nearest adjacent wall, preferably on the right.

Mounting height shall be 60 inches (1524 mm) above the finish floor to the center line of the sign. Mounting location shall be determined so that a person may approach within 3 inches (76 mm) of signage without encountering protruding objects or standing within the swing of a door.

**NOTE:** See also Section 1115B.5 for additional signage requirements applicable to sanitary facilities.

#### Reason

In 1117B.5.7 (Mounting location and height) the  $1^{st}$  sentence is incorrectly worded, which is causing misunderstanding regarding proper installation and application for Braille signage. 1117B.5.7 is amended to correct the  $1^{st}$  sentence to avoid confusion in the application of mounting location for signs by correcting the words 'latch outside of the door' to now read 'latch <u>side</u>, of the door'.

l	Notes:
l	
l	
l	
l	
l	

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

#### **SECTION 1117B - OTHER BUILDING COMPONENTS**

1117B.5 Signs and Identification

1117B.5.11 Cleaner air symbol.

1117B.5.11.2 Conditions of use. Use of the ... is met.

- 1. Floor or wall coverings, floor ... the previous 12 months.
- 2. Incandescent lighting ... or path of travel.
- 3. Heating, ventilation, air condition in... occupant or user.
- 4. To maintain "cleaner-air" ... use or application.
- 5. Signage shall be posted ... or path of travel.
- **6.** A log shall be maintained ... designation. The log shall also include the product label as well as the <u>Material material</u> Safety Data Sheets (MSDS).

#### Reason

In 1117B.5.11.2 (Conditions of use) item 6 the reference to "material" Safety Data Sheets the word 'material' should begin with a capital letter. DSA is proposing to correct the word material to begin with the capital letter M (Material).

Notes:		

#### **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

## **SECTION 1117B – OTHER BUILDING COMPONENTS**

**1117B.6 Controls and Operating Mechanisms.** See also Sections 210-7(g), 380-8(c) and <u>760-16</u> <del>760-9</del>, California Electrical Code, for electrical installation.

- 1. General. Controls and ...this section.
- 2. Clear floor space. Clear floor space ... equipment.
- 3. Height. The highest operable ... above the floor.

**EXCEPTION:** These requirements do not ... by building occupants.

4. Operation. Controls and operating ... 5 pounds (22.2 N) of force.

## Reason

In 1117B.6 (Controls and Operating Mechanisms) the cross reference to 760-9 is incorrect. DSA/AC is proposing to correct the cross reference to read 760-16.

Notes:			

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

#### **SECTION 1117B – OTHER BUILDING COMPONENTS**

1117B.7 Automated Teller Machines and Point of Sale Machines.

**1117B.7.2 General.** Where ATMs are provided for the public, they shall comply with this section. **EXCEPTIONS**:

- 1. In grocery ...
- 2. Where the ...
- **3.** In existing buildings, these regulations shall not apply when legal or physical constraints would not allow compliance with these regulations or equivalent facilitation without creating an unreasonable hardship. See Section 101.17.11, <u>Item</u> 5 <u>Item</u> 4.
- 4. Drive-up-only ...
- 5. Card reading...

## Table 11B-5 (Maximum Reach Depth for Automated Teller Machines)

NOTE: See Figure 11B-5F(d) Figure 11B-5D(d).

## Reason

In 1117B.7.2 (General) in Exception 3 the cross-reference to 101.17.11 Item 4 is incorrect. DSA/AC is proposing to correct the cross-reference to read 101.17.11 Item 5.

In the Note below **Table 11B-5 (Maximum Reach Depth for Automated Teller Machines)** the cross-reference to Figure 11B-5 D (d) is incorrect. DSA/AC is proposing to correct the cross-reference in the Note to read Figure 11B-5F (d).

Notes:		

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

#### SECTOIN 1118B - SPACE ALLOWANCE AND REACH RANGES

**1118B.1** Wheelchair Passage Width. The minimum clear width for single wheelchair passage shall be 32 inches (813 mm) at a point and 36 inches (914 mm) continuously. See Figure 41B-12.

**1118B.2** Width for Wheelchair Passing. The minimum width for two wheelchairs to pass is 60 inches (1524 mm). See Figure <u>11B-12</u> 11B-11.

**1118B.5** Forward Reach. If the clear floor space allows only forward approach to an object, the maximum high forward reach allowed shall be 48 inches (1219 mm) [see Figure 11B-5C (b)]. The minimum low forward reach is 15 inches (381 mm). If the high forward reach is over an obstruction, reach and clearances shall be as shown in Figure 11B-5C(a)(b).

#### Reason

In 1118B.1 (Wheelchair Passage Width) the cross reference to Figure 11B-12 is incorrect. DSA/AC is proposing to correct the cross-reference to read Figure 11B-10.

In 1118B.2 (Width for Wheelchair Passage) the cross reference to Figure 11B-12 is incorrect. DSA/AC is proposing to correct the cross-reference to read Figure 11B-11.

In 1118B.5 (Forward Reach) the cross reference to Figure 11B-5C (a) is incorrect. DSA/AC is proposing to correct cross-reference to read Figure 11B-5C (b).

Notes:		

## **Proposed Amendment**

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

#### **SECTION 1120 – FLOORS AND LEVELS**

1120B.1 Floors Within Each Story. In buildings and facilities, ... lifts.

#### **EXCEPTIONS:**

- **1.** In existing ... facilitation is provided.
- 2. In existing ... for new buildings only.
- **3.** In existing buildings, this section shall not apply when legal or physical constraints would not allow compliance with this section or equivalent facilitation without creating an unreasonable hardship. See Section 101.17.11, Item 5 Item 4.
- 4. Where specifically exempted in other portions of this code.

#### Reason

In 1120B.1 (Floors Within Each Story) in Exception 3 the cross-reference to "Section 101.17.11, Item 4" is incorrect. DSA/AC is proposing to correct the cross-reference to read Item 5.

Not	es:			

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

## SECTION 1127B - EXTERIOR ROUTES OF TRAVEL

1127B.1 General. Site development and ...

Exceptions: 1. Where

1. In existing buildings ...

NOTE: See Section 101.17.11, Item 4 Item 5.

**1127B.4 Outside Stairways.** Where stairways occur outside a building, refer to Sections 1006.17 of the 1995 California Building Code, <u>4120A.4.3</u> <u>1115A</u> and 1133B.4.4.

#### Reason

In **1127B.1** (General) in the Note the cross-reference to "Section 101.17.11, Item 4" is incorrect. DSA/AC is proposing to correct cross-reference to read 101.17.11 Item 5.

In **1127B.4 (Outside Stairways)** the cross-reference to 1120A.4.3 is incorrect. DSA/AC is proposing to amend the cross-reference to read <u>1115A</u> and 1133B.4.4.

Notes:			

## **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1128B - PEDESTRIAN GRADE SEPARATIONS (OVERPASSES AND UNDERPASSES)

Pedestrian ramps on ... and a usable pathway.

## **EXCEPTIONS:**

- 1. When the grade ... complied with.
- 2. For existing ... unreasonable hardship.

NOTE: See Section 101.17.11, Item 5 Item 4.

#### Reason

In 1128B (Pedestrian Grade Separations (Overpasses and Underpasses)) in the Note the cross-reference to "Section 101.17.11, Item 4" is incorrect. DSA/AC is proposing to correct cross-reference to read 101.17.11 Item 5.

Notes:		

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

## **SECTION 1130B - PARKING STRUCTURES**

All entrances to and vertical ... accessible parking spaces.

#### **EXCEPTIONS:**

- **1.** Where the enforcing ... is provided.
- **2.** This section shall not apply to existing buildings where the enforcing agency determines that, due to legal or physical constraints, compliance with these regulations or equivalent facilitation would create an unreasonable hardship. See Section 101.17.11, <a href="https://linearchy.com/line

## Reason

In **1130B (Parking Structures)** in Exception 2 the cross-reference to "Section 101.17.11, Item 4" is incorrect. DSA/AC is proposing to correct cross-reference to read 101.17.11 Item 5.

Notes:
Proposed Amendment
PART 2 - CHAPTER 11B [For DSA/AC] ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC
ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING
SECTION 1133B – GENERAL ACCESSIBILITY FOR ENTRANCES, EXITS AND PATHS OF TRAVEL
<b>1133B.1.1.1.1</b> (see related changes to 1117B.5.1)
4422D 2 Doore
1133B.2. Doors. 1133B.2.3 Hinged Doors.
1133B.2.3.1 Pairs of Doors.
1133B.2.3.2 Automatic doors. When an automatic
EXCEPTIONS:
1. The provisions of following shall apply:
Where the occupant in clear width.
Where occupant load in clear width.
2. In existing buildings, the provisions of this section shall not apply when legal or physical constraints will
not allow compliance with these building standards or equivalent facilitation without creating an unreasonable hardship. See Section 101.17.11, <u>Item 5</u> <del>Item 4</del> .
unicasonable hardship. dee dection 101.11.11, <u>item o</u> <del>item 1</del> .
Reason
In 1133B.2.3.2 (Automatic doors) in exception 2 the cross-reference to "Section 101.17.11, Item 4" is incorrect.
DSA/AC is proposing to correct cross-reference to read 101.17.11 Item 5.
Notes:

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1133B - GENERAL ACCESSIBILITY FOR ENTRANCES, EXITS AND PATHS OF TRAVEL

1133B.3 Corridors, Hallways and Exterior Exit Balconies.

- 1133B.3.1 Corridor and hallway widths.
- 1133B.3.2 Corridors and hallways over 200 feet (60,960 mm). Corridors and hallways that ... **EXCEPTIONS:** 
  - 1. In existing buildings, ...
  - 2. In existing buildings, the provisions of this section shall not apply when legal or physical constraints will not allow compliance with these building standards or equivalent facilitation without creating unreasonable hardship. See Section 101.17.11, Item 5 Item 4.

## Reason

In 1133B3.2 (Corridor and hallways over 200 feet (60 960 mm)) in the 'mm' conversion for 200 feet, a comma is

reference to "Section 101.17.11, Item 4" is incorrect. DSA/AC is proposing to correct cross-reference to read 101.17.11 Item 5.
101.17.11 item 5.
Notes:
Proposed Amendment
PART 2 - CHAPTER 11B [For DSA/AC] ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING
SECTION 1133B – GENERAL ACCESSIBILITY FOR ENTRANCES, EXITS AND PATHS OF TRAVEL 1133B.4 Stairways.
1133B.4.2 Handrails G <u>c</u> onfiguration. 1133B.4.2.6 Handgrips.
1133B.4.2.6.1 The handgrip portion
EXCEPTIONS: 1. In existing buildings
<ol> <li>These regulations shall not apply in existing buildings where legal or physical constraints will not allow compliance with these regulations or equivalent facilitation without creating an unreasonable hardship. See Section 101.17.11, <a href="Item 4">Item 5</a> Item 4.</li> </ol>
Reason
In <b>1133B.4.2.6.1</b> in Exception 2 the cross-reference to "Section 101.17.11, Item 4" is incorrect. DSA/AC is proposing to correct cross-reference to read Item 5.
Materia
Notes:

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1133B – GENERAL ACCESSIBILITY FOR ENTRANCES, EXITS AND PATHS OF TRAVEL 1133B.4 Stairways

1133B.4.3 Tactile stair level identification signage Tactile stair level identification signs that comply with 1117B.5 
Item 1 1117B.1-B shall be located at each floor level landing in all enclosed stairways in buildings two or more stories in height to identify the floor level. At exit discharge level, the sign shall include a raised five pointed star located to the left of the identifying floor level. The outside diameter of the star shall be the same as the height of the raised characters.

#### Reason

In 1133B.4.3 (Tactile stair level identification sign) the word 'sign' in the title is incorrect. DSA/AC is correcting the word to read 'signage'. The cross-reference to "1117B.1-B" is incorrect. DSA/AC is proposing to correct cross-reference to read 1117B.5 Item 1.

Notes:			

## **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1133B – GENERAL ACCESSIBILITY FOR ENTRANCES, EXITS AND PATHS OF TRAVEL 1133B.4 Stairways

1133B.4.5 Treads, nosing and risers.

**1133B.4.5.3 Open risers are not permitted.** On any given ... the horizontal. **EXCEPTIONS:** 

- 1. In existing buildings, ...
- **2.** These regulations shall not apply to existing buildings when legal or physical constraints will not allow compliance with these regulations or equivalent facilitation without creating an unreasonable hardship. See Section 101.17.11, <u>Item 5</u> <u>Item 4</u>.

#### Reason

In 1133B.4.5.3 (Open risers are not permitted) in exception 2 the cross-reference to "Section 101.17.11, Item 4" is incorrect. DSA/AC is proposing to correct cross-reference to read Item 5.

Notes:	

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1133B – GENERAL ACCESSIBILITY FOR ENTRANCES, EXITS AND PATHS OF TRAVEL 1133B.5 Ramps

1133B.5.4 Landings.

**1133B.5.4.1 Location of landings.** Level ramp landings shall be provided at the top and bottom of each ramp. Intermediate landings shall be provided at intervals not exceeding 30 inches (762 mm) of vertical rise and at each change of direction. Landings are not considered in determining the maximum horizontal distance of each ramp. Landing shall be level as specified in the definition of "level area" in Section 1102B Section 202.

1133B.5.4.3 Encroachment of doors. See Section 1003.3.4.4 1133B.5.4.1.

## Reason

In 1133B.5.4.1 (Location of landings) the cross-reference to "Section 202" is incorrect. DSA/AC is proposing to correct cross-reference to read Section 1102B.

In **1133B.5.4.3 (Encroachment of doors)** the cross-reference to "Section 1133B.5.4.1 is incorrect, which contains absolutely no information at all regarding the encroachment of doors. DSA/AC is proposing to correct cross-reference to read 1003.3.4.4.

Notes:			

## **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1133B – GENERAL ACCESSIBILITY FOR ENTRANCES, EXITS AND PATHS OF TRAVEL 1133B.5 Ramps

1133B.5.6 Wheel auides. ...

**1133B.5.6.2** A wheel guide rail shall be provided, centered 3 inches (76 mm) plus or minus 1 inch (25 mm) above the surface er-of the ramp.

**1133B.5.7** Ramps more than 30 inches (762 mm) above the adjacent ground shall be provided with guardrails as required by this section and Section 1003.3.4.6. Such guardrails shall be continuous from the top of the ramp to the bottom of the ramp.

#### Reason

In 1133B.5.6.2 the word 'or' in the sentence is misspelled. DSA/AC is proposing to correct the spelling to read 'of' in the sentence.

In 1133B.5.7 cross-reference to "and Section 1003.3.4.6" is incorrect. DSA/AC is proposing to delete the cross-reference.

Notes:			

PART 2 – CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

# SECTION 1133B – GENERAL ACCESSIBILITY FOR ENTRANCES, EXITS AND PATHS OF TRAVEL 1133B.5 Ramps

**1133B.5.7** Ramps more than 30 inches ...

1133B.5.7.3 Height. The top of guardrails shall not be less than 42 inches (1067 mm) in height.

## **EXCEPTIONS:**

- 1. The top of guardrails for Group R, Division 3 ...
- 2. The top guardrails on a balcony immediately ...
- **3.** The top of guardrails for stairways, exclusive of their landings, may have a height as specified in Sections <u>4129A.4.1 1123A.6.1</u> and 1133B.4.1.1 for handrails.

Where an elevation... the aisle floor shall be provided.

**EXCEPTION:** Where the backs of seats on the front of the cross aisle project 24 inches 610 mm) or more above the adjacent floor of the aisle, a guardrail quardrail-need not be provided.

The top of guardrails ... and 36 inches (914 mm) otherwise.

#### Reason

In 1133B.5.7.3 (Height) in the Exception to the 2nd paragraph the word "quardrail" is misspelled. DSA/AC is proposing to correct the spelling of the word to read "guardrail".

Notes:			

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1133B – GENERAL ACCESSIBILITY FOR ENTRANCES, EXITS AND PATHS OF TRAVEL 1133B.7 Walks and Sidewalks.

**1133B.7.1 Continuous surface.** Walks and sidewalks subject to these regulations shall have a continuous common surface, not interrupted by steps or by abrupt changes in level exceeding 1/2 inch (12.7 mm) (see Section 1133B.7.4 4133B.7.3), and shall be a minimum of 48 inches (1219 mm) in width. Surfaces shall be slip-resistant as follows:

## Reason

In 1133B.7.1 (Continuous surface) the cross-reference to "Section 1133B.7.3" is incorrect. DSA/AC is proposing to correct cross-reference to read 1133B.7.4.

Notes:		

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1133B – GENERAL ACCESSIBILITY FOR ENTRANCES, EXITS AND PATHS OF TRAVEL 1133B.7 Ramps more than 30 inches ...

1133B.7.1 Guardrails

**1133B.7.1.3 Surface cross slopes.** Surface cross slopes shall not exceed 1/4 inch (6 mm) per foot except when the enforcing agency finds that due to local conditions it creates an unreasonable hardship, the cross slope shall be increased to a maximum of 1/2 inch (12.7 mm) per foot for distances not to exceed 20 feet (6096 mm) (4.16 % 2.5% gradient).

EXCEPTION: When, because ... 36 inches (914 mm).

#### Reason

In 1133B.7.1.3 (Surface cross slopes) the cross-reference to "2.5% gradient" is incorrect. DSA/AC is proposing to correct cross-reference to read 4.16 % gradient.

Notes:			

#### **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1133B - GENERAL ACCESSIBILITY FOR ENTRANCES, EXITS AND PATHS OF TRAVEL

1133B.7 Ramps more than 30 inches ...

**1133B.7.2 Gratings.** Walks, sidewalks and ... of traffic flow.

## **EXCEPTIONS:**

- 1. Where the enforcing ...
- **2.** This section shall not apply in those conditions where, due to legal or physical constraints, the site of the project will not allow compliance with these building standards or equivalent facilitation without creating an unreasonable hardship. See Section 101.17.11, <u>Item 5 Item 4.</u>

#### Reason

In 1133B.7.2 (Gratings) in exception 2 the cross-reference to "Section 101.17.11, Item 4" is incorrect. DSA/AC is proposing to correct cross-reference to read Item 5.

Notes:	

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

# SECTION 1134B - ACCESSIBILITY FOR EXISTING BUILDINGS

1134B.2 General. ...

**1134B.2.1** A primary entrance ... public telephones serving the area.

**EXCEPTIONS:** 

**2.4** Other buildings and facilities... accessible level.

**NOTE:** For the general privately funded multistory building exception applicable to new construction and alterations, see Section 1103B.1, <u>Exception 3</u> <u>Exception 2.1.</u>

#### Reason

In **1134B.2.1** in the Note under Exception 2.4 the cross-reference to "Section 1103B.1, Exception 2.1" is incorrect. DSA/AC is proposing to correct cross-reference to read Exception 3.

Notes:	

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

SECTION 1134B – ACCESSIBILITY FOR EXISTING BUILDINGS 1134B.3 General Accessibility for Entrances, Exits and Paths of Travel. 1134B.3.1 Automatic doors. When an automatic ....

- **EXCEPTIONS:**1. In existing buildings the following shall apply:
  - 1.1 Where the occupant load is less than 10, except ...
  - **1.2** Where occupant load is greater than 10 and it is determined that compliance with Section 4120A.2.3 1132A.2.1 would create an unreasonable hardship, doorways may be 30 inches (762 mm) in clear width.
- **2.** In existing buildings, the provisions of this section shall not apply when legal or physical constraints will not allow compliance with these building standards or equivalent facilitation without creating an unreasonable hardship. See Section 101.17.11, <a href="https://linearchynthia.com/lin

#### Reason

In **1134B.3.1 (Automatic doors)** in Exception 1.2 the cross-reference to 1120A.2.3 is incorrect. DSA/AC is amending to read 1132A.2.1 to be consistent with HCD Chapter 11A. In exception 2 the cross-reference to "Section 101.17.11, Item 4" is incorrect. DSA/AC is proposing to correct cross-reference to read 101.17.11 Item 5.

es:		

## **Proposed Amendment**

PART 2 – CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

Figure 11B-1A (Multiple Toilet Stall) see Reason

#### Reason

In **Figure 11B-1A (Multiple Toilet Stall)** the titles of figures for Single Occupancy Toilet and Multiple Toilet Stall are incorrect. DSA/AC is amending the cross-references to the Figures to read Single <u>Accommodation</u> Occupancy Toilet to be consistent with section 1115B.7.2 and Multiple <u>Accommodation</u> Toilet Stall to be consistent with section 1115B.7.1.

The 60-inch minimum width for multiple toilet stall was left out of figure. DSA/AC is proposing to correct the diagram by including cross-reference for minimum width for multiple toilet stall to 60"- min. .

The cross-reference in the Side Elevation figure to 33" is incomplete. DSA/AC is amending the cross-reference to read '33" to center line', and added in this dimension line. The 36" and 42" grab bar cross-references in the Side Elevation are incorrect. DSA/AC is amending the cross-references to read 36" Min and 42" Min.

Notes:		

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

Figure 11B-1B (Multiple Accommodation Toilet) see Reason

#### Reason

In **Figure 11B-1B (Multiple Accommodation Toilet)** the 60-inch minimum width for multiple accommodation toilet stall was left out of figure. DSA/AC is proposing to correct the diagram by including cross-reference for minimum width for multiple accommodation toilet stall to 60"- min

Notes:		

#### **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

Figure 11B-1D (Knee Clearance) see Reason

## Reason

Figure 11B-1D (Knee Clearance) the side elevation diagram cross-reference to 34" min. is incorrect. DSA/AC is proposing to correct cross-reference to 34"- max. DSA/AC is also giving the side view a title "Side Elevation." The plan view diagram cross-reference to 19" min. is incorrect. DSA/AC is proposing to correct cross-reference to 19"-max. DSA/AC also added at the 18" min the words "to centerline", and added in this dimension line.

Notes:		

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

Figure 11B-2A (Roll-in Shower) see Reason

Figure 11B-2B (Roll-in Shower) see Reason

Figure 11B-2C (Open Shower) see Reason

#### Reason

In **Figure 11B-2A (Roll-in Shower)** for Roll-In Shower—A and Plan Roll-in Shower—C under the 60" dimension lines, 30" dimension lines, and 36" dimension line the word 'Min" is in the wrong place. DSA/AC is proposing to move the word 'Min" to above the dimension line to read '60" Min', 30" Min and 36" Min. The acronym used (CL) is unclear in these figures. DSA/AC is proposing to spell out what (CL) actually means 'Center Line' and changed the dimension lines to indicate 'center line'. The ½" Max. Beveled cross-references are incomplete. DSA/AC is proposing to correct to read '1/2" Beveled Threshold'.

The Elevation At Shower Typical for A-C diagram the cross-reference to 46" max. is incorrect. DSA/AC is proposing to correct cross-reference to 40" max. Reference to the single lever mixing valve control is missing. DSA/AC is proposing to add an arrow indicating where the 'Single Lever Mixing Valve Control' is to be placed.

In **Figure 11B-2B (Roll-in Shower)** in the Perspective of Roll-in Shower—B the height of the control cross-reference to 46" Max. is incorrect. DSA/AC is proposing to correct cross-reference to read: <u>40"</u> Max. For clarity the words 'folding seat' were moved down to line up with the arrow pointing to the folding seat. The single lever mixing valve control is show but not identified. DSA/AC is proposing to add an arrow and identifying the 'Single Lever Mixing Valve Control'. In the Roll-in Shower—B the wording for the arrow to the threshold of ½" Max. Beveled is incomplete. DSA/AC is proposing to correct the reference to read '½" Beveled Threshold'.

In **Figure 11B-2C (Open Shower)** section diagram reference to 46" max. is incorrect. DSA/AC is proposing to correct reference to <u>40"</u> max. For clarity DSA/AC added the dimension line for the top of hose mounting bracket. The title of Section diagram is incorrect. DSA/AC is proposing to correct the name of this diagram to read 'Elevation'. In the Plan diagram the cross-reference to title for grab bar dimension of 36" Min. and 24" Min. Length are incorrect. DSA/AC is amending the grab bar title dimension to read 36" Grab Bar and 24" Min. Grab Bar.

Notes:	

# PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

In Figures 11B-14A, 11B-14B, 11B-14C titles of all figures are incorrect. Proposing to correct title of each figure as follows:

Figure 11B-14A - International TTY Symbol

INTERNATIONAL SYMBOL OF ACCESS FOR HEARING IMPAIRED

Figure 11B-14B - Volume Control Telephones

INTERNATIONAL SYMBOL OF ACCESS FOR HEARING IMPAIRED

Figure 11B-14C—<u>International Symbol of Access For Hearing Loss</u>

INTERNATIONAL SYMBOL OF ACCESS FOR HEARING IMPAIRED

ı	R	6	а	S	n	n

Notes:		

## **Proposed Amendment**

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

Figure 11B-18A Double Parking Stalls – see Reason

Notes:

#### Reason

In **Figure 11B-18A** (**Double Parking Stalls**) section diagram reference to 18" and 8" are incorrect. DSA/AC is proposing to correct reference to <u>18-feet</u> and <u>8-feet</u>. The placement of painting the words "NO PARKING" within the accessible parking stall is unclear. DSA/AC is proposing to correct the figure to more clearly identify, at the bottom within the loading and unloading access aisle paint the words "NO PARKING" in 12" high letters min. The dimension of where to begin measuring for the 9' stall width is unclear. Figures are amended to include that the stall dimension is to the centerline of the stripe for other than unloading and loading access aisle striping.

PART 2 - CHAPTER 11B [For DSA/AC] -- ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING

Figure 11B-18B Single Parking Stalls – see Reason

for other than unloading and loading access aisle striping.

## Reason

In Figure 11B-18B (Single Parking Stalls) the placement of painting the words "NO PARKING" within the accessible parking stall is unclear. DSA/AC is proposing to correct to more clearly identify, at the bottom within the loading and unloading access aisle paint the words "NO PARKING" in 12" high letters min. The dimension of where to begin measuring for the 9' stall width is unclear. Figures are amended to include that the stall dimension is to the centerline of the stripe for other than unloading and loading access aisle striping.

Notes:
Proposed Amendment
PART 2 - CHAPTER 11B [For DSA/AC] ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC
ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING
Figure 11B-18C Diagonal Parking Stalls – see Reason
Reason
In Figure 11B-18C (Diagonal Parking Stalls) section diagram reference to 18" is incorrect. DSA/AC is proposing to
correct reference to 18-feet. The placement of painting the words "NO PARKING" within the accessible parking stall
is unclear. DSA/AC is proposing to correct to more clearly identify, at the bottom within the loading and unloading
access aisle paint the words "NO PARKING" in 12" high letters min. The dimension of where to begin measuring for
the 9' stall width is unclear. Figures are amended to include that the stall dimension is to the centerline of the stripe

Notes:

PART 2 - CHAPTER 11B [For DSA/AC] ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING		
Figures for Curb Cut Details – see Reason		
Reason		
In <b>Figures for Curb Cut Details 11B-20A, 20B, 20C and 20 D</b> the cross reference to Sec. 1127B.5.10 is incorrect with the amendments in this rulemaking in 1127B.5. DSA/AC is amending the cross-reference in these Figures to read 1127B.5.9.		
Notes:		
Notes:		
Proposed Amendment		
PART 2 - CHAPTER 11B [For DSA/AC] ACCESSIBILITY TO PUBLIC BUILDINGS, PUBLIC ACCOMMODATIONS, COMMERCIAL BUILDINGS, AND PUBLICLY FUNDED HOUSING  Figure 11B-23A Truncated domes – see Reason		
- igano : i = zor: i i unoutou uomoo oo noutou		
Reason		
In Figure 11B-23A (Truncated Domes) (see related changes to 1127B.5 #8)		
Martan		
Notes:		

# PART 2 – CHAPTER 11C -- STANDARDS FOR CARD READERS AT GASOLINE FUEL DISPENSING FACILITIES

## SECTION 1101C - CARD-READER DEVICES AT FUEL DISPENSING EQUIPMENT

**1101C.1 General.** Notwithstanding other requirements in the California Building Code (CBC), only the requirements and additional definitions in this section shall apply to card—reading devices in motor vehicle fuel facilities, except that administrative requirements which are found in Chapter 1 still apply.

For purposes of this section, the following additional definitions shall apply:

ACCESSIBLE. See 11A, Section 1102A.1-A 1107A.1-A and Chapter 11B, Section 1102B.

INTERNATIONAL SYMBOL OF ACCESSIBILITY. See Chapter 11A, Section <u>4102A.9-1</u> <u>1107A.9-1</u> and Chapter 11B, Section 1102B.

LEVEL AREA See Chapter 11A, Section 1102A.12-L 1107A.12-L and Chapter 11B, Section 1102B

#### Reason

Chapter 11C (Standards for Card Readers at Gasoline Fuel Dispensing Facilities) several cross-references in Chapter 11C are incorrect, as HCD is renumbering 11A regulations. DSA/AC is amending the cross-references to be consistent with the new numbering format of Chapter 11A.

	Notes:		
١			

#### PART 2 - CHAPTER 30 -- ELEVATORS, DUMBWAITERS, ESCALATORS AND MOVING WALKS

#### **SECTION 3001 - SCOPE**

The provisions of this chapter shall apply to the design, ...

**[For DSA/AC] EXCEPTION:** For accessibility requirements for special access lifts, see California Code of Regulations, Title 24, Part 7, Article 7-15, Sections 7-3093 through 7-3094.5 and Part 2, Sections 4110A-1124A and 1116B.

**3001.1** [For DSA/AC & HCD 1 and HCD 1/AC] Referenced Standards. For elevators and special access lifts in covered multi-family dwellings see Chapter 11A, Section <u>4110A\_1124A</u> For accessibility requirements for elevators and special access (wheelchair) lifts in public accommodations, commercial buildings, and publicly funded, owned or leased housing, see Chapter 11B, Section 1116B.

#### **SECTION 3003 - SPECIAL PROVISIONS**

#### 3003.4 Size of Cab and Control Locations.

**3003.4.1 General.** In buildings three or more stories ...

**[For DSA/AC] EXCEPTION:** For accessibility requirements for size of cab and control locations in accessible housing, see Chapter 11A, Section <u>4110A.1.2</u> <u>1124A.3</u> and for public buildings, public accommodations, commercial buildings, and publicly funded housing, see Chapter 11B, Section 1116B.1.1.

**3003.4.2 Operation and leveling.** The elevator shall be automatic and ...

**[For DSA/AC] EXCEPTION:** For accessibility requirements for operation and leveling in accessible housing, see Chapter 11A, Section <u>4110A.1.3</u> <u>1124A.10</u>. For public buildings, public accommodations, commercial buildings and publicly funded housing, see Chapter 11B, Section 1116B.1.2.

3003.4.5 Door protective and reopening device. Doors closed by automatic means ...

**[For DSA/AC] EXCEPTION:** For accessibility requirements for door protective and reopening device in accessible housing, see Chapter 11A, Section 1114A.1 1124A.9. For public buildings, public accommodations, commercial buildings, and publicly funded housing, se Chapter 11B, Section 1116B.1.5.

#### 3003.4.6 Door delay (passenger service time).

3003.4.6.1 Hall call. The minimum acceptable time from ...

**[For DSA/AC] EXCEPTION:** For accessibility for hall call in accessible housing, see Chapter 11A, Section <u>4110A.1.5</u> <u>1124A.7.1</u>. For public buildings, public accommodations, commercial buildings and publicly funded housing, see Chapter 11B, Section 1116B.1.6.

3003.4.6.2 Car call. The minimum acceptable time ...

**[For DSA/AC] EXCEPTION:** For accessibility requirements for car call in accessible housing, see Chapter 11A, Section <u>4110A.1.6</u> <u>1124A.7.2</u>. For public buildings, public accommodations, commercial buildings and publicly funded housing, see Chapter 11B, Section 1116B.1.7.

3003.4.8 Car controls. Controls shall be readily accessible ...

**[For DSA/AC] EXCEPTION:** For accessibility requirements for car controls in accessible housing, see Chapter 11A, Section <u>1110A.1.8</u> <u>1124A.3.3</u>. For public buildings, public accommodations, commercial buildings and publicly funded housing, see Chapter 11B, Section 1116B.1.9.

**3003.4.13 Minimum illumination.** The minimum illumination at the car controls ...

**[For DSA/AC] EXCEPTION:** For accessibility requirements for minimum illumination at car controls in accessible housing, see Chapter 11A, Section <u>1110A.1.10</u> <u>1124A.5</u>. For public buildings, public accommodations, commercial buildings and publicly funded housing, see Chapter 11B, Section 1116B.1.12.

3003.4.15 Hall lantern. A visual and audible signal ...

**[For DSA/AC] EXCEPTION:** For accessibility requirements for hall lantern in accessible housing, see Chapter 11A, Section <u>1110A.1.11</u> <u>1124A.6.</u> For public buildings, public accommodations, commercial buildings and publicly funded housing, see Chapter 11B, Section 1116B.1.14.

**3003.4.16 Doorjamb marking.** The floor designation shall be provided at ...

**[For DSA/AC] EXCEPTION:** For accessibility requirements for doorjamb marking in accessible housing, see Chapter 11A, Section 1110A.1.12 1124A.8. For public buildings, public accommodations, commercial buildings and publicly funded housing, see Chapter 11B, Section 1116B.1.15.

#### 3003.4.17 Location.

**[For DSA/AC] EXCEPTION:** For accessibility requirements for location of passenger elevators in accessible housing, see Chapter 11A, Section <u>4110A.1.13</u> <u>1124A.2</u>. For public buildings, public accommodations, commercial buildings and publicly funded housing, see Chapter 11B, Section 1116B.1.16.

#### Reason

Chapter 30 (Elevators, dumbwaiters, Escalators and Moving Walks) several cross-references in Chapter 30 are incorrect, as HCD is renumbering 11A regulations. DSA/AC is amending the cross-references to be consistent with the new numbering format of Chapter 11A.

Notes:			

#### **Proposed Amendment**

PART 3 - Article 406 -- Receptacles, Cord Connectors, and Attachment Plugs (Caps)

406.3 General Installation Requirements.

406.3(G) Installation Heights.

[DSA/AC] - Installation Heights. Where access for ... platform.

**Exception No. 1:** Receptacle outlets installed as part of permanently installed baseboard heaters are exempt.

**Exception No. 2:** Required receptacle outlets shall be permitted in floors when adjacent to sliding panels or walls.

**Exception No. 3:** Baseboard electrical outlets used in re-locatable partitions, window walls or other electrical convenience floor outlets are not subject to the minimum height requirements.

**Exception No. 4:** This section shall not apply to existing buildings when the enforcing agency determines that compliance with these standards would create an unreasonable hardship.

#### Reason

Existing Exceptions to 406.3(G) are missing. During the 2002 Code Adoption Cycle section 210.7(g) was renumbered and relocated to 406.3(G). During the renumbering and relocating Exceptions 1—5 were unintentionally left in the old section 210.7(g). This proposed change is to be made to DSA/AC's adoption of the 2002 National Electrical Code and will not take effect until the effective date of the 2004 Title 24 triennial edition. DSA/AC is proposing to purposely relocate Exceptions 1—5 to the correct location, which is 406.3(G).

Notes: